Servicing / Technical bulletin number: 095

Issued to: Service Network. (all service stations)

Date Issued: Nov 2025

Subject: UML Pro-sensor Elite (PSE) Capsule Mis-molded issue.

Issued by: Guy Page (Technical)

Exp date: open

Please Note

We have had a report that a UML Pro-sensor Elite capsule has been found with the main housing mis-molded, (please see image below)
The water entry holes at the end of the capsule have not been fully cleared and would prevent the water from activating the unit.

Please ensure that when checking the auto capsule while servicing or inspecting a lifejacket that the unit is as follows.

- That the expiry date is sufficient to reach the next service requirement.
- That the unit is not damaged or fired.
- That the water entry holes are clear.

If you find any component damaged (outside normal use) or looks like it has a manufacturing defect, please report back to Crewsaver. (ASAP)

If you have any questions, please contact: -
Guy Page
Training and Technical Support Manager,
Survitec Group Guy.page@survitecgroup.com