


## FIBRELIGHT RECOVERY CRADLE

**OPERATIONS MAINTENANCE MANUAL** 



- 1. Inspection checklist, as required by SOLAS regulation 20.7, to include: -
- Wear and damage to the sewn eyes at each end of the Fibrelight Cradle
- Wear and damage to the horizontal and vertical webbings.
- Wear and damage to the stitching.
- 2. The Fibrelight Cradle must be returned to Survitec Group for all repair or replacement.
- 3. A competent person must carry out regular inspections.
- 4. A log must be maintained of all inspections and maintenance.

DATE EXAMINED	DATE EXAMINED	
DATE EXAMINED	DATE EXAMINED	



**GET IN TOUCH** 

www.survitecgroup.com