



Servicing / Technical bulletin number: 090

Issued to: Service Network (**Halo**)

Date Issued: March 2025

Subject: Change to HALO operating Head torque wrench (Halkey Roberts)

Issued by: Guy Page (Technical)

Exp date: open

Change to Crewsaver operating Head torque wrench 10439

Note:-

The supplier of the calibrated torque wrench part code 10439 has stopped manufacture to this item.

This has been replaced by a new version of the torque wrench and a T-Bar.

They will be supplied under the same Part code. (10439)

The T-bar replaces the welded $\frac{1}{4}$ drive point on the head of the old tool, that was used to remove the nut from Halkey Roberts (HR) Heads.



Standard socket

The New version tool is supplied with the Standard 9/16 socket which is required when removing the HR operating Heads

Single socket code R47240



Please ensure the correct approved tools are used for removal and replacement of the operating head. Failing to do this will result in damage to the lifejacket.

NOTE. The old version tool is still approved to use and does not need to be changed.

If you have any questions, please contact: -

Guy Page

Training and Technical Support Manager,

Survitec Group

guy.page@survitecgroup.com